


- ~ LEGEND ~
- SPK SET PK NAIL
  - SIR SET IRON ROD
  - SRHS SET RAILROAD SPIKE
  - SDH SET DRILL HOLE
  - SMAG SET MAG NAIL
  - FRPS FOUND RAILROAD SPIKE
  - FIP FOUND IRON PIPE
  - FDMON FOUND DAMAGED MONUMENT
  - FDIP FOUND DAMAGED IRON PIPE
  - FIR FOUND IRON ROD
  - FMAG FOUND MAG NAIL
  - SNBW SET NOTCH IN BACK OF WALK
  - FAI FOUND ANGLE IRON
  - FSQR FOUND SQUARE ROD
  - FDH FOUND DRILL HOLE

REVISIONS:


Copyright © - This drawing is not to be altered or reproduced without the written approval of the Surveyor. Any changes made to this document will render it null and void.



CERTIFIED - SHEETS 1 THROUGH 4:  
*John A. Doyle*  
 INDIANA REGISTERED PROFESSIONAL LAND SURVEYOR NO. 9564

**JOHN A. DOYLE & ASSOCIATES**  
 INCORPORATED  
 2322 E. MICHIGAN BLVD., MICHIGAN CITY, INDIANA  
 PHONE: (219) 872-2321 FAX: (219) 879-3887  
 EMAIL: JOHNADOYLE@COMCAST.NET  
 - CIVIL ENGINEERS AND LAND SURVEYORS -  
 REGISTERED IN INDIANA & MICHIGAN

~ PLAT OF SURVEY ~  
 BLOCKS 2, 3, 6 AND PART OF BLOCK 10 IN  
 DUNCAN'S ADDITION AND PART OF BLOCK 20 IN  
 ELSTON'S ORIGINAL SURVEY ALL  
 IN MICHIGAN CITY, LAPORTE COUNTY, INDIANA

DATE:  
 September 05, 2017  
 FILE NO.  
 EOS-Duncans-17.dwg  
 SHEET  
 1 OF 4

D:\V\_080077\_11.32 EOS-DUNCANS-17.DWG

FB 17-1, Pg. 37-47, Date=2017/EOS-DUNCANS-17.dwg